

# PODKŁADKI


PAD FOR FORMING PRESS

## PODKŁADKI PEŁNE L=835

SOLID PADS L=835



| SYMBOL CODE       | A mm | B mm | L mm |
|-------------------|------|------|------|
| U92-LI-25X25X835  | 25   | 25   | 835  |
| U92-LI-50X50X835  | 50   | 50   | 835  |
| U92-LI-50X75X835  | 50   | 75   | 835  |
| U92-LI-50X100X835 | 50   | 100  | 835  |




## PODKŁADKI Z OTWOREM L=835

HOLLOW PADS L=835



| SYMBOL CODE       | A mm | B mm | L mm | OTWÓR / SLOT mm |
|-------------------|------|------|------|-----------------|
| U92-LF-25X25X835  | 25   | 25   | 835  | Ø10             |
| U92-LF-50X50X835  | 50   | 50   | 835  | Ø25             |
| U92-LF-50X75X835  | 50   | 75   | 835  | 20X45           |
| U92-LF-50X100X835 | 50   | 100  | 835  | 20X60           |



## PODKŁADKI TRÓJKĄTNE Z OTWOREM L=835

TRIANGULAR PADS WITH HOLE L=835



| SYMBOL CODE      | B mm | L mm | OTWÓR / SLOT mm |
|------------------|------|------|-----------------|
| U92-LT-35X50X835 | 50   | 835  | Ø10             |

